

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

475
NNW
1/2-1
0.744 mi.
3927 ft.

99 BAY 47TH STREET
99 BAY 47TH STREET
BROOKLYN, NY

NY Spills S109061527
N/A

Relative:
Higher

Actual:
7 ft.

SPILLS:

Name: 99 BAY 47TH STREET
Address: 99 BAY 47TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0800207 / 2008-04-07
Facility ID: 0800207
Facility Type: ER
DER Facility ID: 345435
Site ID: 395924
DEC Region: 2
Spill Cause: Deliberate
Spill Class: C2
SWIS: 2401
Spill Date: 2008-04-05
Investigator: vszhune
Referred To: Not reported
Reported to Dept: 2008-04-05
CID: 78
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Fire Department
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: Not reported
Remediation Phase: 0
Date Entered In Computer: 2008-04-07
Spill Record Last Update: 2009-04-29
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: Not reported
Spiller Company: 001
Contact Name: PAUL BIDE
DEC Memo: "04/05/08-Zhune responded to this site. A 275 waste oil gallons tank was abandoned on the side walk of a church catholic school (Most Preciuos Blood School) at Bay 47 street between Harway st and Bay st. Some oil was spill on the street. The Fire Department capped the tank and put speedy-dry on the spill. Milro picked up the thank, two drums and did the clean up. 04/07/08-Zhune contacted Anna Russo from Most preciuos school (718) 3737343 trying to find out who is the responsible to abandon the tank. Anna said that they did not know anything and refered me to the rectory of the Church (718) 3728022.

Genie said we did not even know until somebody came asking if there was a fire becouse the Fire Department was outside. She said the church did not dump the tank. After discusion with Randy Austin spill closed and no responsible party found. 05/02/08-Vought-Received analyticals from Milro (Basso) and request to sign Statement that DEC reviewed analyticals and belief that they are accurate. Vought signed statement and will discuss with DEC Tibbe who lives in proximity to Milro office to possibly signed generator manifest. Analyticals show that oil also contained methyl ethel ketone, TCE, 4-methylphenol, PCB-1248, aresenic and as such must be disposed of as Hazardous Waste. Final ISR sent up by DEC Zhune on 4/23/08 however after due to

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

the above information DEC has not received bill from contractor. Vought called DEC Ferrar and requested that he hold ISR until final bill received. Ferrar requested that new Final ISR be sent up once bills received from Milro. 05/08/08-Vought-Received message from Milro Basso requesting EPA Generator ID number. Vought inquired to DEC Farrar who forwarded inquiry to DEC Johnson who said that Jack Hoyt in EPA Region 2 (212-637-4106) should be contacted for number. Vought called Hoyt and left message to return call to Vought. 05/27/08-Vought-Received phone call from Milro Basso that he obtained EPA Generator ID number from EPA. 05/27/08-Vought-Contract Payment Package (Test America)-Drum sample analysis (04/08/08-04/23/08.) 07/25/08-Zhune Contract Payment Package Milro Associate - cut and cleaned one 275 AST and removed from site. Transport and dispose of one 55 gallon drum of waste oil and one 55 gallon of contaminated debris (4/5/08-4/5/08.) 04/29/09-Vought-Final ISR needs to be issued for this site even though no RP as tank was abandoned on sidewalk with no owner in front of church. "

Remarks:

"Someone dumped a 275 gallon tank on the side of the road with waste oil and fled the scene. Some has spilled out of the drum. They are in the process of offloading the tanks. 17:48 caller called back stating this is near a school and he needs a call back ASAP. Message left for rep on her cell phone. 18:45 - Maurice of the Office of Emergency Management called. Would like a call back to 718-422-8700 with an ETA of the rep. Rep contacted and advised to call, rep also confirmed that she got the prior message. "

All Materials:

Site ID: 395924
Operable Unit ID: 1152867
Operable Unit: 01
Material ID: 2143639
Material Code: 0022
Material Name: waste oil/used oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 10.00
Units: G
Recovered: .00
Oxygenate: Not reported